

DISCLAIMER

This document was prepared solely for general guidance. Neither B.C. Transmission Corporation, the British Columbia Control Area Operator, the Transmission Facility Owner nor any of their employees or agents make any representations, express or implied, to any third parties as to:

1. the merchantability or fitness for any particular purpose of,
2. the accuracy, completeness or usefulness of, or
3. property rights of any person in, any information, product or process disclosed in this report.

B.C. Transmission Corporation does not accept any liability of any kind arising in any way out of the use of, or reliance by any third party on any information, product or process described in this document. This document may be reproduced in whole or in part by any means whatsoever without the express written permission of B.C. Transmission Corporation, the BCCAO or the TFO.

Force Outage Data for 2L309 (GMS - SNK) from 2003-1-1 to 2007-12-31									
ACC	Event Type/ Number	Event For	Event Start	Actual Completion	Event Duration	Description	Cause	Cust./ Still Out	Comment/Condition
NCC	Forced Outage 6-031303	2L309	2004/06/09 10:42	2004/06/09 10:43	1 min	All Out	Unknown Cause	1564 0	
NCC	Forced Outage 6-031835	2L309	2004/08/05 01:39	2004/08/05 01:39	<1 min	All Out	Lightning	1549 0	
NCC	Forced Outage 6-033750	2L309	2005/06/01 13:00	2005/06/01 14:49	1 hr 49 min	All Out	Defective Equipment	1608 0	Forced outage due to GMS - 2CVT1 connection failed.
NCC	Forced Outage 6-033759	2L309	2005/06/01 09:32	2005/06/01 09:32	<1 min	All Out	Defective Equipment	1608 0	This was the original fault on 2L309, when 2CVT1 connection faulted causing an outage, with auto reclose.
NCC	Forced Outage 6-037603	2L309	2006/09/20 13:11	2006/09/20 13:18	7 min	All Out	Unknown Cause	1662 0	2L309 and 2L313 kicked out, successful automatic reclose SNK 2CB21 remained open. Supervisory reclose attempt was successful SNK 2CB2.
NCC	Forced Outage 1-041855	2L309	2003/06/29 12:31	2003/06/29 12:36	5 min	All Out	Lightning	1510 0	2L309 KO and reclosed manually--Lightning in the GMS area
NCC	Forced Outage 1-041994	2L309	2003/07/12 19:03	2003/07/12 19:07	4 min	All Out	Lightning	1510 0	2L309 ko and closed in manually at SNK and at TLR
NCC	Forced Outage 1-042000	2L309	2003/07/12 19:09	2003/07/12 19:16	7 min	All Out	Lightning	1510 0	2L309 KO AND RECLOSED AUTO GMS MANUALLY AT TLR Protection sheets indicate with 2L309. SNK 2CB1, 2CB11 & 2CB21 should have tripped as well, but didn't.

Force Outage Data for 2L313 (SNK - TLR) from 2003-1-1 to 2007-12-31									
Orig. CC	Event Type/ Number	Event For	Event Start	Actual Completion	Event Duration	Description	Cause	Cust./ Still Out	Comment/Condition
NCC	Forced Outage 6-040366	2L313	2007/06/04 16:31	2007/06/04 16:31	<1 min	All Out	Lightning	1679 0	
NCC	Forced Outage 6-040372	2L313	2007/06/04 16:41	2007/06/04 16:41	<1 min	All Out	Lightning	1682 0	
NCC	Forced Outage 6-040373	2L313	2007/06/04 16:46	2007/06/04 16:46	<1 min	All Out	Lightning	1682 0	
NCC	Forced Outage 6-040374	2L313	2007/06/04 16:48	2007/06/04 16:48	<1 min	All Out	Lightning	1682 0	
NCC	Forced Outage 6-040375	2L313	2007/06/04 17:14	2007/06/04 17:14	<1 min	All Out	Lightning	1682 0	
NCC	Forced Outage 6-040376	2L313	2007/06/04 17:19	2007/06/04 17:19	<1 min	All Out	Lightning	1682 0	